Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

441 POLE T-11 NY Spills S107657574
WSW WEST 24 STREET & MERMAID AVENUE N/A

WSW WEST 24 STREET & MERMAID AVENUE 1/2-1 BROOKLYN, NY

0.698 mi. 3684 ft.

Relative: SPILLS:
Higher Name: POLE T-11

Actual: Address: WEST 24 STREET & MERMAID AVENUE

2 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0514167 / 2006-04-17

 Facility ID:
 0514167

 Facility Type:
 ER

 DER Facility ID:
 311013

 Site ID:
 360822

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C4

 SWIS:
 2401

 Spill Date:
 2006-03-10

 Investigator:
 GDBREEN

 Referred To:
 Not reported

 Reported to Dept:
 2006-03-10

 CID:
 409

Water Affected:

Spill Source:

Commercial/Industrial
Spill Notifier:

Cleanup Ceased:

Cleanup Meets Std:

Last Inspection:

Not reported

Responsible Party

Not reported

False

Not reported

Recommended Penalty: False UST Trust: False Remediation Phase: 0

Date Entered In Computer: 2006-03-10 Spill Record Last Update: 2006-06-12

Spiller Name: ERT DESK MIKE DAUGHTERY
Spiller Company: CON EDISON POLE T-11
Spiller Address: WEST 24 ST/ MERMAID AVE

Spiller Company: 999

Contact Name: ERT DESK MIKE DAUGHTERY

DEC Memo: "04/17/06 - See e-docs for Con Ed report detailing cleanup and

closure. 04/17/06 - See e-docs for Con Ed report detailing cleanup

and closure. 163294. see eDocs."

Remarks: "1 PINT THAT HASNT BEEN CLEANED UP. TRANSFORMER ENVOLVED ON O

CONCRETE. CON ED# 163294"

All Materials:

Site ID: 360822 Operable Unit ID: 1117937 Operable Unit: 01 Material ID: 2108450 Material Code: 0541A Material Name: dielectric fluid Case No .: Not reported Material FA: Petroleum Quantity: Not reported

Units: G Recovered: .00

Oxygenate: Not reported